

Common Release Notes Q5 2.3 / Q6 3.3

System Interface Panel

Added AcuAir HD Support

- Added the option to add the AcuAir HD Unity product to the SIP.

Common Release Notes Q5 2.2 / Q6 3.2

System Interface Panel

Chromium Error

- Fixed a bug that was causing an “Aw Snap” error in the Chromium browser when an AcuAir or Compressor unit entered a running state.

Running Indication Icons

- Changed the icons used to represent units in a running/stopped state to a “play” and “stop” symbol.

Alarm Display Bug

- Fixed an issue that would cause alarms to persist after completing the “Remove Setpoints” operation on the Configuration Page.

Common Release Notes Q5 2.1 / Q6 3.1

System Interface Panel

Upgrade Fix

- Fixed an issue that was causing the Upgrade Process to not function in version 3.0.

Note: This version can only be obtained by receiving a new Flash Card as the Upgrade Process cannot be completed on Q6 Version 3.0.

HD Unity Support

- Added the option to add HD Unity products to the SIP (Evaporator, Condenser, Compressor and Engine Room).